MIDNIGHT SUN DRILLING CO. LTD.
PH: 668-2434
WHITEHORSE Y.T.
P.O. Box 4391

FIELD REPORT

#8020300024

Started June 13 ..... 19 77
Completed ... June 13 .... 1977 ..

NAME AND ADDRESS OF CLIENT	DESCRIPTION OF WORK	LOCATION OF WORK
Stanley and Associates 212 Main St. Whitehorse, Y.T.	#2 Test Well	Junction of 3/11 hwys.

FORMATION LOG

FROM	TO	FORMATION
0'	1'	fill
1'	2'	peat
2'	16'	gravel
16'	20'	silty sand
20'	83'	silty sand till
83'	86'	silty sand till rocks
86'	107'	silty sand till

DESCRIPTION OF WORK	TIME DATE	FROM	TO	HOURS
MOVE				
moved from #1 to #2 hole and setting-up drilled to 107'	June 13	8am	10pm	12
moved to #3 hole				

Rcrd. of Casing & Pipe

Size	Type	Size	Type
6"			
Feet	Inch	Feet	Inch
20'			

Remarks: Reamed to 7 7/8" to 16'.
Set 6" to 20' and pulled
drilled from 20' to 107'

STATIC LEVEL
Ground level moving
Top of casing

Total Rig Time 10 hrs.
~~Total Standby~~ 3 hrs.
Drilling Mud 4 sacks

SIGNATURES

MIDNIGHT SUN.....
TITLE.....

CLIENT. R. J. Stewart.....
TITLE.....