PROJECT: 952-15231

RECORD OF BOREHOLE: BH95G-23

SHEET 1 OF 1

LOCATION: 6815275N, 414906E, PIT AREA (SOU.CEN.)

DRILLING DATE: Aug. 10, 1995

DATUM: NAD 83

INCLINATION: -90 AZIMUTH:

DRILL RIG: Boyles Brothers - Rotary

DRILLING CONTRACTOR: D.J. Drilling

FR-FRACTURE, CL-CLEAVAGE, SH-SHEAR, VN-VEIN; F-FAULT, J-JOINT, P-POLISHED, S-SLICKENSIDED; SM-SMOOTH, R-ROUGH, ST-STEPPED, PL-PLANAR; FL-FLEXURED, UE-UNEVEN, W-WAVY, C-CURVED

DEPTH SCALE METRES	DESCRIPTION	ELEV. DEPTH (m)	RUN No.	PENETRATION RATE (m/min.)	FLUSH	COLOUR % RETURN	RECOVERY TOTAL CORE %	RECOVERY SOLID CORE %	R.Q.D. %	FRACT. INDEX PER 0.3m	DISCONTINUITY DATA: DIP w.r.t. CORE AXIS	DISCONTINUITY DATA: TYPE AND SURFACE DESCRIPTION	ROCK STR. (MPa)	WEATHERING INDEX (w)	NOTES / TEST RESULTS
0	Ground Surface	1386.21													
	Compact to dense SAND, some silt, some gravel to silty SAND and GRAVEL, occasional cobbles to boulders. ... becoming more coarse with depth.	0.00	1												Aug. 26 1995 Native Backfill
2			2												Bentonite Seal
4			3												
6			4												
8			5												
9			6												Sand Pack
10		1376.15													
	Dense to very dense, moist, grey, silty SAND and GRAVEL to SAND some gravel, some silt, boulders and cobbles.	10.06	7												32mm dia. PVC Screen
12			8												
13			9												Slough
14		1372.04													
	Bedrock - mux - chlorite - calcite SCHIST with biotite porphyioblasts sill - mafic - strong foliation, high calcite content (15%).	14.17 1371.58	9									P/PL-R			
15	End of Borehole	14.63													
16															
17															
18															
19															
20															

DATA FORM: ROCKMV6

DATA INPUT: BAD-SEPT '95

DEPTH SCALE: 1 to 100

CLIENT: Cominco

Golder Associates

LOGGED: L.P.

DATE: Aug. 10, 1995

CHECKED: C.J.C.