RECORD OF BOREHOLE: BH95G-21

PROJECT: 952-15231
LOCATION: 6815640N, 414802E, PIT AREA WEST
INCLINATION: -90 AZIMUTH:

DRILLING DATE: Aug. 9, 1995
DRILL RIG: Boyles Brothers - Rotary
DRILLING CONTRACTOR: D.J. Drilling

SHEET 1 OF 1
DATUM: NAD 83

FR-FRACTURE, CL-CLEAVAGE, SH-SHEAR, VN-VEIN
F-FAULT, J-JOINT, P-POLISHED, S-SLICKENSIDED
SM-SMOOTH, R-ROUGH, ST-STEPPED, PL-PLANAR
FL-FLEXURED, UE-UNEVEN, W-WAVY, C-CURVED

DEPTH SCALE METRES	DRILLING RECORD	DESCRIPTION	SYMBOLIC LOG	ELEV. DEPTH (m)	RUN No.	PENETRATION RATE (m/min.)	FLUSH / COLOUR / % RETURN	RECOVERY TOTAL CORE %	RECOVERY SOLID CORE %	R.Q.D. %	FRACT. INDEX PER 0.3m	DISCONTINUITY DATA: DIP w.r.t. CORE AXIS	DISCONTINUITY DATA: TYPE AND SURFACE DESCRIPTION	ROCK STR. (MPa)	WEATHERING INDEX (w)	NOTES / TEST RESULTS
0		Ground Surface		402.74												
		TOPSOIL		0.15	1											
1		Compact to dense, moist, brown, silty fine SAND, some gravel, occasional cobble.														
				400.74												
2				2.00	2								J/B-PL-S/R			Bentonite Seal
3																Aug. 26, 1995
4					3								J/B-PL-S/R			
5		Bedrock - moderately strong, slightly weathered light grey SCHIST.														
6					4								B-PL/I-S/R			Sand Pack
7																32mm dia. PVC Screen
					5								broken			
8													B-PL/R-S/R			
9					6								B-PL-S/R			
				392.68												
10		End of Borehole		10.06												
11																
12																
13																
14																
15																
16																
17																
18																
19																
20																

DATA FORM: ROCKMV6
DATA INPUT: BAD-SEPT'95

DEPTH SCALE:
1 to 100

CLIENT: Cominco

Golder Associates

LOGGED: L.P.
DATE: Aug. 9, 1995
CHECKED: C.J.C.