FARO
L-SECTION - 17+000 (PANEL
GEOLOGICAL INTERPRETATION
1" = 50'
JAN/86 (R.S.T.)

116+000E 117+000E 117+070E 118+000E 119+000E 120+000E 121+000E 122+000E 122+020E 123+015E 124+022E

4200 4000 3800 3600 3400 3200 3000

76-11 SECTION OFFSET=5
76-10 SECTION OFFSET=7
76-09 SECTION OFFSET=12
76-11 SECTION OFFSET=34
76-10 SECTION OFFSET=26
76-09 SECTION OFFSET=60

3D 3A IDO IOE ICD

'117' DYKE
'P' FAULT
'J' FAULT
'K' FAULT

IEO/ID2 ID4/2L 2BCD 2BD5 2EF 2AO 2EH 2BD 2AC

LEGEND

- Fault(inferred) with relative movement.
- Fault(assumed) with relative movement.
- Lithologic Contact(defined).
- Lithologic Contact(inferred).
- Lithologic Contact(assumed).
- Contact of sericite/white mica alteration with host rock.
- Piercing point of ddh through section.
- Lithologic Contacts above pit surface.
- Fault movement away from observer.
- Fault movement towards observer.

GEOLOGICAL INTERPRETATION
(ANVIL CODES)

INTERPRETED BY	DATE	DRAWN BY	DATE	PLOT RATIO 1" = 600 UNITS= FEET	PANEL NO=
R.S.T.	JAN. 1986	T.M.	JAN. 1986	DRAWN BY= PROGRAM DH070	
				PLUNGE CORRECTION= NO	
				1 AUG 1985 10:51 AM	1
				COORDINATE SYSTEM= MINE SURVEY	

CYPRUS ANVIL MINING CORPORATION
!THE IMPERIAL ANVIL!
VERTICAL LONG SECTION 17+000
45 DEG VIEW AZIMUTH 135 DEG PROFILE

50 0 50 100 150 Feet

This reference scale bar has been added to the original drawing. The scale of the same may not be the same as the image, therefore it should be used as a reference for the original size.

YUKON GEOLOGICAL SURVEY

000226

(86)-FA-287-85