

Author	CI Report/Date	Name of Report
SRK #1204	July 22, 1992	Reclaim Dam and Camp Creek Diversion, Sä Dena Hes Mine, Yukon Territory - Comments On
SRK #60642	July 24, 1992	Investigation and Surveillance Programme Faro Pit, Faro
P.A. Harder	July 1991	Fish Habitat Development and Enhancement Opportunities in Rose Creek
Cominco Eng. File P66.6	Sept. 24, 1992	Performance Evaluation Report for the Grum/Vangorda Water Treatment Plant
Golder #912-1144	Sept. 30, 1992	Construction Drawings and Documents for Stronsay Tailings Storage Facility - Stage 1
Golder #912-2406	May 1992	Down Valley Tailings Area - 1991 Construction Projects, Faro
SRK #101204	July 1992	Design Report, South Dam Extension Sä Dena Hes Mine, Yukon
	WH92-09 December 1992	SDH Temporary Closure Plan
	WH92-10	Sä Dena Hes Mineral Inventory - August 1, 1992
SRK #S-101104	Nov. 12, 1992	Sä Dena Hes Inspection Report, Reclaim Dam Spillway and Camp Creek Diversion Reconstruction
	WH92-11	J. Zbeetnoff Field Report (?)
SRK #160649	December 7, 1992	Expansion of the Vangorda Mine Rock Containment Facility 0 Vangorda Plateau Development
Rescan	January 1993	Stronsay Project - Baseline Environmental Monitoring Report
Lakefield #4400	Jan. 22, 1993	Water Treatment Sludge Characterization and Disposal Plan
Rescan	January 1993	Advanced Exploration and Development of the dy Underground Mine - Project Description
	WH93-01 January 1993	Claim/Lease Holdings for Curragh Inc., Curragh Mining Properties, 833051 Ontario Ltd., Stronsay Corporation - 2 figures, 11 sets of multi-page tables, 2 maps* for Faro DN - 3 figures, 1 multi-page table for Sä Dena Hes - 3 figures, 1 table for Stronsay * An-An-8701 and AN-AN-93-006
	WH93-02	Sä Dena Hes 1992 Annual Report to YTWB, License IN90-002

Author	CI Report/Date	Name of Report
K.R. McClay	WH91-14 Feb 1990 Mar 1991 Jun 1991	Structural Evaluation of the Cirque Orebody - NE B.C. Part 1: Underground Mapping Part 2: Underground Mapping Part 3: Structural Geology and Petrography
Kilborn #8385-15	WH91-15	Stronsay Corp - Project #8385-15 - Preliminary Engineering Assessments and Cost Estimate for Upgrading the Access Roads from the Stronsay Mine to Chowika Barge Loading Site
SRK #60643	December 1991	Sulphate Reduction as a Water Treatment Alternative at the Faro Minesite
L. C. Pigage	WH92-01	Faro Waste Dump Mapping
P.A. Harder	WH92-02 January 1992	Vangorda Creek Aquatic Studies - 1990 Data Report
E. Pengal	WH92-03 February 1992	SDH 1991 Annual Report to the Water Board - License IN90-002
Jilson	WH92-04 April 1992	Claim Status Report to Pelly River Mines Limited (NPL)
Dale Miner	WH92-05 May 1992	Y.A.T. Site Investigation Report
D. Brown	WH92-06/3 March 1992	Geology of the Vangorda Pb-Zn-Ag Deposit
SRK #60644	WH92-07 April 1992	Faro Tailings Decommissioning Plan - Tailings Covers Test Facility 1991 Monitoring Report
P. Harder	WH92-08 May 1992	Proposal to Examine Stream Community Responses to a Gradient of Zinc Add'ns in Vangorda Creek (EDA Submission)
SRK #60648		Summary Report on Schedule D to Water License IN89-001 - Faro Mine (unbound original) cc GA/Chantal/File/WB
SRK #60646	August 1992	Sulphate Reduction at Faro - Preliminary Lab Evaluation (unbound original + 2 copies) cc GA/Chantal
SRK #60644	August 1992	Tailings covers Test Facility 1991 Monitoring Report (Faro Decommissioning Plan)
Cominco Eng. File P66.6	Oct. 14, 1992	Contingency Plan and Sludge Stability Plan for the Grum/Vangorda Water Treatment Plant

Author	CI Report/Date	Name of Report
	WH90-34	Vangorda Plateau Project IEE Addendum
SRK	WH90-35	Mt. Hundere Final Geotechnical Investigations - Mill and Tailings
Boojum	WH90-36 May 1990	Vangorda Plateau Development - Notes on Geochemistry and Hydrology
Rescan	WH90-37 Sept 1990	Status Report - Cirque Project
	January 1991	Curragh Resource Inc - Faro Division Mineral Inventory at January 1, 1991 (Caution - Confidential - Do not use or distribute without Vice-president authorization.)
	WH91-02	Stronsay Reserves
	WH91-03 December 1991	Dy Mineral Inventory
	WH91-04A	SDH Spill Contingency Plan - Revised March, 1992
	WH91-05	Progress Report on Schedule D to Water License #IN89-001
	WH91-06	YAT Site Investigation Report
	WH91-07	Reprocessing Tailings - Appendix C, Report WH91-008
	WH91-08	Faro Decommissioning - Overview of the Environmental Plans
P.A. Harder	WH91-09	Overview Assessment of Fish Resources in Blind Ck. Drainage
Golder #892-1159	WH91-10	Alternative Mill Site - Stronsay Project
Golder #892-1159	WH91-11	Stage 1 Level Geotechnical - Stronsay Project
SRK #60635		Down Valley Tailings Decommissioning Plan
Kilborn #3509-28		Water Recycle and Tailings Deposition Plan
Rescan		Cirque Environmental Impact Statement
Laberge Environmental Services	WH91-12 December 1991	Biological Monitoring Programme at Vangorda Creek, Faro, Yukon 1991
SRK #01203	WH91-13 January 1992	As-Built Construction Report - North, South and Reclaim Dams Sā Dena Hes Mine, Yukon Territory

Author	CI Report/Date	Name of Report
C. Reed	WH89-17	Summary Report on the Mt. Hundere Property Structure (Appendix B, Vol. V of MHJV IEE)
	WH90-01	Impact Assessment of Fish Toxicity in Vangorda Creek
	WH90-02	Vangorda Plateau Supplement to Water License
SRK #60609	WH90-03	Vangorda Plateau Development Project Mitigation and Treatment Cost for Closure
Bradford	WH90-05	Vangorda Plateau and Part of Swim Basin
	WH90-07	Northwest of Faro Minesite
	WH90-09	Catfish Mineral Property
	WH90-10	Cirque Claims
	WH90-11	Mt. Hundere Test Pits and Property Access
	WH90-12	Mt. Hundere IEE - Volume VI
	WH90-13	Mt. Hundere IEE - Volume IV
	WH90-14	Faro Mine 1989 Annual Report to the Water Board
	WH90-15	Mt. Hundere Water License Application
	WH90-16	Mt. Hundere Preliminary Geotechnical Investigation - Mill and Tailings
	WH90-17	Baseline Studies of Fishery and Aquatic Resources
	WH90-18	Mt. Hundere IEE - Volume V
SRK #60616	WH90-19	Mt. Hundere Water License Application - Vol. II
	WH90-20	Mt. Hundere - Vol. III, Socio-economics
	WH90-21	Mt. Hundere IEE - Vol. II, Mine Access Road
	WH90-22	Induced Polarization Survey - Tutshi Lake, B.C.
	WH90-26	Vangorda Plateau Review of Alternative Abandonment Plans
	WH90-27	Vangorda Plateau Review of Zinc Toxicity and Water Quality
Coopers & Lybrand	WH90-30	Curragh's Socio-Economic Contribution to the Yukon
	WH90-31	Vangorda Plateau Development Facts - Sheets #1 thru 10

ORIGINAL DOCUMENTS LISTING

Revised July, 1993
d:\data\jilson\origdoc.lst

Author	CI Report/Date	Name of Report
L.C. Pigage	WH87-01	Geological Report RR Claim Group
	WH88-01	Catfish Iguana Assessment
McLenehan/Bowers	WH88-02	Faro Mine Abandonment
	WH88-03	Abandonment Submission and Summary Report
Eamer	WH88-04	Review of Peak Flow Estimates for Rose and Vangorda Creeks
L.C. Pigage	WH88-05	Geological and Drilling Report Northwest of the Faro Mine Site
Vintillas	WH88-06 March 1988	Preliminary Open Pit Reserve Evaluation for the Swim Pb-Zn-Ag Deposit near Faro, Yukon
C. Reed	January 1989	Curragh Geological and Mine Reserves - Jan. 1, 1989
	WH89-01	Haul Road Construction
	WH89-02	1989 Faro Northwest Report
Davis	WH89-03	Geology of Catfish Mineral Property, Tutshi Lake, B.C.
	WH89-04	Tread Claims - 1989 Report
	WH89-05	21989 POD Orthophoto Report
	WH89-06	Dy Shaft Pilot Hole
	WH89-09	Vangorda Plateau W.L. Application - Vol. I Appendices
	WH89-10	Vangorda Plateau W.L. Application - Vol.II Appendices
	Wh89-11	Vangorda Plateau W.L. Application - Vol. III Figures
	WH89-12	Vangorda Plateau IEE - Vol. I, Stage 2 - Report
	WH89-13	Vangorda Plateau IEE - Vol. II, Stage 2 - Appendices
	WH89-14	Vangorda Plateau IEE - Vol.III, Stage 2 - Rpt. Figures
J.H. Davis	WH89-15	Status Report on the Carmacks Coal Properties - Tantalus, Tantalus Butte and Five Finger Mines
Burns	WH89-16	A Preliminary Literature Review on the Toxicity of Zinc