



BEMA INDUSTRIES LTD.

19790-88 Ave. P. O. Box 4  
Langley 005934 30-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500 E - 153 N <del>500 E - 153 N</del> (1)	DRILL HOLE NO. 1	DATE 1 OCT 1978
SAMPLE DEPTH 1.2 m	SAMPLERS MJB/DL	CONTRACT Kent Addison
LINE 500 E	STATION 153 N	LOCATION FINLAYSON PELLY

## SAMPLE DESCRIPTION

COLOUR	Black
TEXTURE	Gravel. DRY
SOIL TYPE	
FRAGMENTS	Shale?
MINERALOXIDE	Nil

## DRILLING TIME

POINT STARTED	10:30	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	11:00

REMARKS: 3m N of PK 78-1



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. <del>18-2</del> N/S	DRILL HOLE NO. 1	DATE 1 OCT 78
SAMPLE DEPTH	SAMPLERS MJB/DL	CONTRACT Kerr Addison
LINE 500E	STATION 153N	LOCATION Finlayson - Pelly

## SAMPLE DESCRIPTION

COLOUR	/
TEXTURE	
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED <del>11:00</del>	SAMPLER STARTED 11:00
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 11:15

**REMARKS:** Hit water + gravel or sand at 2m. did not compact & lost sample.



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. <del>500E-153N</del> ②	DRILL HOLE NO. 1	DATE 1 Oct 78
SAMPLE DEPTH 2.8 m	SAMPLERS MJB/DL.	CONTRACT Kerry Addison
LINE 500E	STATION 153 N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Black
TEXTURE	Silty - Gravel.
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	SAMPLER STARTED 11:15
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 11:30

## REMARKS:

HIT HARD GROUND 2.5 m.  
permafrost?



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-153N <del>75</del> (3)	DRILL HOLE NO. 1	DATE 1 OCT 1978
SAMPLE DEPTH 4.0 m	SAMPLERS MJB/DL	CONTRACT Kerr Addison
LINE 500E	STATION 153N	LOCATION Finlayson - Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey -
TEXTURE	Bedrock
SOIL TYPE	—
FRAGMENTS	weathered Fe stain & banded
MINERALOXIDE	in sampler

## DRILLING TIME

POINT STARTED	11:30	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	12:15

## REMARKS:

Very hard ground  
sample consists of almost 100%  
rock frags.



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E - 121N ①	DRILL HOLE NO. 2	DATE 1 Oct 1978
SAMPLE DEPTH 1.2 m	SAMPLERS M.J.B/O.L.	CONTRACT Kerr Addison
LINE 500E	STATION 121N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey
TEXTURE	Gravel. w. clay
SOIL TYPE	
FRAGMENTS	shale?
MINERALOXIDE	N.I.

## DRILLING TIME

POINT STARTED	SAMPLER STARTED 1:05
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 1:15

## REMARKS:



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-121N 2	DRILL HOLE NO. 2	DATE 1 Oct 78
SAMPLE DEPTH 3.0 m	SAMPLERS MJB/DL	CONTRACT Kerr Addison
LINE 500E	STATION 121N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey
TEXTURE	Bedrock - Very hard
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	1:15	SAMPLER STARTED
POINT STOPPED		SAMPLER STOPPED
POINT EXTRACTED		SAMPLER EXTRACTED 2:00

**REMARKS:** 500E-121N 2 is Bedrock.  
Sample 500E-121N 2A is split from  
one sample & represents soil above  
bedrock sample.



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E 117 1	DRILL HOLE NO. 3	DATE 1 Oct 78
SAMPLE DEPTH 3.0 m	SAMPLERS	CONTRACT Kerr Addison
LINE 500E	STATION 117N	LOCATION Finlayson - Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey - Brown
TEXTURE	Gravelly or broken weathered
SOIL TYPE	bedrock - 1
FRAGMENTS	shale with clayey matrix
MINERALOXIDE	Fe stain

## DRILLING TIME

POINT STARTED	2:00	SAMPLER STARTED
POINT STOPPED		SAMPLER STOPPED
POINT EXTRACTED		SAMPLER EXTRACTED 2:40

**REMARKS:**

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-117N #2	DRILL HOLE NO. 3	DATE 1 OCT 78
SAMPLE DEPTH 4.0 M	SAMPLERS MSB/DL	CONTRACT Keff Addison
LINE 500E	STATION 117N	LOCATION Finlayson - Pelly

**SAMPLE DESCRIPTION**

COLOUR	Grey-brown
TEXTURE	bedrock
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	Fe stain

**DRILLING TIME**

POINT STARTED	2:40	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	350

**REMARKS:** Bedrock steeply Dipping  
E or W.  
Sampler jammed by fine  
bedrock material. ~~Had~~ Had to put  
sampler down twice

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-92N #1	DRILL HOLE NO. 4	DATE 1 Oct 78
SAMPLE DEPTH 1.2 m	SAMPLERS MJB/DL	CONTRACT Kerr Addison
LINE 500E	STATION 92N	LOCATION Finlayson Pelly

**SAMPLE DESCRIPTION**

COLOUR	Grey-Green
TEXTURE	Gravelly rounded frags.
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	N.L.

**DRILLING TIME**

POINT STARTED	<del>4:15</del>	SAMPLER STARTED	4:15
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	4:25

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E - 92N #2	DRILL HOLE NO. 4	DATE 1 OCT 78
SAMPLE DEPTH 3.1m	SAMPLERS MJB/DL	CONTRACT Kerr Addison
LINE 500E	STATION 92N	LOCATION Finlayson - Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey
TEXTURE	Gravelly w. clay matrix
SOIL TYPE	very soft.
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	4:25	SAMPLER STARTED	✓
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	4:35

## REMARKS:

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. <i>500E-92N #3</i>	DRILL HOLE NO. <i>4</i>	DATE <i>1 OCT 78</i>
SAMPLE DEPTH <i>3.9 m</i>	SAMPLERS <i>MJB/DL</i>	CONTRACT <i>Kerr, Addison</i>
LINE <i>500E</i>	STATION <i>92N</i>	LOCATION <i>Firleyson - pelly</i>

**SAMPLE DESCRIPTION**

COLOUR	<i>(3) bedrock chips black</i>
TEXTURE	<i>with white clayey matl.</i>
SOIL TYPE	<i>(3A) matl above bedrock poss</i>
FRAGMENTS	<i>also weathered S.R. Sn</i>
MINERALOXIDE	<i>Fe stained - acetad.</i>

**DRILLING TIME**

POINT STARTED <i>4:55</i>	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED <i>5:35</i>

**REMARKS:**

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-62N #1	DRILL HOLE NO. 5	DATE 1 OCT 78
SAMPLE DEPTH 1.2 m	SAMPLERS MJB/DL	CONTRACT Kerr Addison
LINE 500E	STATION 62N	LOCATION Finlayson - Pelly

**SAMPLE DESCRIPTION**

COLOUR	Black
TEXTURE	FINE Muck!
SOIL TYPE	Swamp muck.
FRAGMENTS	N/I
MINERALOXIDE	N/I

**DRILLING TIME**

POINT STARTED	SAMPLER STARTED 5:50
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 6:00

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E - 62N #2	DRILL HOLE NO. 5	DATE 1 OCT 78
SAMPLE DEPTH 3.2M	SAMPLERS MJB/DL	CONTRACT Kerr Addison
LINE 500E	STATION 62N	LOCATION Finlayson - Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey
TEXTURE	Sandy
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	6:00	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	6:30

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R. 4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. <i>500E-62N # 3</i>	DRILL HOLE NO. <i>5</i>	DATE <i>2 OCT 78</i>
SAMPLE DEPTH <i>4.8 M</i>	SAMPLERS <i>MLB/OL</i>	CONTRACT <i>KERR ADDISON</i>
LINE <i>500E</i>	STATION <i>62N</i>	LOCATION <i>FINLAYSON PELLY</i>

## SAMPLE DESCRIPTION

COLOUR	<i>Grey - Brown</i>
TEXTURE	<i>Bedrock</i>
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	<i>Fe stain visible banding</i>

## DRILLING TIME

POINT STARTED	<i>8:30</i>	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	<i>10:25</i>

## REMARKS:



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E 29N #1	DRILL HOLE NO. 6	DATE 2 OCT 78
SAMPLE DEPTH 1.61	SAMPLERS MSB/DL	CONTRACT KERR ADRIAN
LINE 500E	STATION 29N	LOCATION FINLAYSON PELLEY

## SAMPLE DESCRIPTION

COLOUR	Grey - Brown
TEXTURE	Gravelly - Till
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	Nil

## DRILLING TIME

POINT STARTED	SAMPLER STARTED 10:35
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 10:40

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E - 29N #2	DRILL HOLE NO. 6	DATE 2 OCT 78
SAMPLE DEPTH 3.1M	SAMPLERS MJB/DL	CONTRACT Ken Addison
LINE 500E	STATION 29N	LOCATION FINLAYSON - PELLEY

## SAMPLE DESCRIPTION

COLOUR	Grey blue
TEXTURE	soft
SOIL TYPE	clay
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	10:40	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	11:05

**REMARKS:**

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R. 4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-29N #3	DRILL HOLE NO. 6	DATE 20 OCT 78
SAMPLE DEPTH 3.7	SAMPLERS MSB/DL	CONTRACT Kerr Addison
LINE 500 E	STATION 29N	LOCATION Finlayson Pelly

**SAMPLE DESCRIPTION**

COLOUR	Grey
TEXTURE	
SOIL TYPE	Till-clay
FRAGMENTS	
MINERALOXIDE	

**DRILLING TIME**

POINT STARTED	11:05	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	11:55

**REMARKS:**

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-180N #1	DRILL HOLE NO. 7	DATE 2 OCT 78
SAMPLE DEPTH 1.1 m	SAMPLERS MJB/DL	CONTRACT Kerr Addison
LINE 500E	STATION 18N	LOCATION Finlayson Pelly

**SAMPLE DESCRIPTION**

COLOUR	Black
TEXTURE	gravelly with clay
SOIL TYPE	till
FRAGMENTS	
MINERALOXIDE	

**DRILLING TIME**

POINT STARTED	SAMPLER STARTED 12:55
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 1.05

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R. 4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-180N #2	DRILL HOLE NO. 7	DATE 2 Oct 78
SAMPLE DEPTH 3.2m.	SAMPLERS MSB DL	CONTRACT Kerr Addison
LINE 500E	STATION 180N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Black
TEXTURE	
SOIL TYPE	clay TILL
FRAGMENTS	
MINERALOXIDE	Brown & ORANGE SPECKS

## DRILLING TIME

POINT STARTED	1:05	SAMPLER STARTED	1:05
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	1:30

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500 E - 180 N #3	DRILL HOLE NO. 7	DATE 2 OCT 78
SAMPLE DEPTH 4.3 M	SAMPLERS MJB/DL	CONTRACT Kerr Addison
LINE 500 E	STATION <del>500</del> 180 N	LOCATION FINLAYSON PELLEY

## SAMPLE DESCRIPTION

COLOUR	Black
TEXTURE	Till - clay & pebbles
SOIL TYPE	
FRAGMENTS	INTRUSIVE? WITH Fe Pyrite
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	1:30	SAMPLER STARTED
POINT STOPPED		SAMPLER STOPPED
POINT EXTRACTED		SAMPLER EXTRACTED 2:50

**REMARKS:** Very hard ground

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-180N #4	DRILL HOLE NO. 7	DATE 2 OCT 78
SAMPLE DEPTH 5.8 M.	SAMPLERS MJB/DL	CONTRACT Kerr Addison
LINE 500E	STATION 180N	LOCATION FINLAYSON PELHY

**SAMPLE DESCRIPTION**

COLOUR	BLACK
TEXTURE	WEATHERED BEDROCK
SOIL TYPE	SHALE
FRAGMENTS	SOME PEBBLES
MINERALOXIDE	

**DRILLING TIME**

POINT STARTED	2:50	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	4:40

**REMARKS:** VERY HARD GROUND



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-211N #1	DRILL HOLE NO. 8	DATE 2 OCT 78
SAMPLE DEPTH 1.2M	SAMPLERS MJB/DK	CONTRACT KERR ADDISON
LINE 500E	STATION 211N	LOCATION FINLAYSON PELLEY

## SAMPLE DESCRIPTION

COLOUR	GREY-GREEN
TEXTURE	
SOIL TYPE	TILL
FRAGMENTS	SOME PEBBLES
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	SAMPLER STARTED 4:50
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 5:00

## REMARKS:

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R. 4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-211N #2	DRILL HOLE NO. 8	DATE 2 OCT 78
SAMPLE DEPTH 3.0M	SAMPLERS MSB/DK	CONTRACT KERR ADDISON
LINE 500E	STATION 211N	LOCATION FINLAYSON PELLEY

**SAMPLE DESCRIPTION**

COLOUR	GREY-GREEN
TEXTURE	
SOIL TYPE	TILL
FRAGMENTS	Intrusive FRAGMENTS? or quartz
MINERALOXIDE	

**DRILLING TIME**

POINT STARTED 5:00	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 5:45

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-211N #3	DRILL HOLE NO. 8	DATE 2 OCT 78
SAMPLE DEPTH 3.9	SAMPLERS MSB/DL	CONTRACT KERR ADDISON
LINE 500E	STATION 211N	LOCATION FINLAYSON PELLY

## SAMPLE DESCRIPTION

COLOUR	GREY-GREEN
TEXTURE	
SOIL TYPE	TILL
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	5:45	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	6:45

## REMARKS:



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-241N #1	DRILL HOLE NO. 9	DATE 30 OCT 78
SAMPLE DEPTH 1.3m	SAMPLERS MJB/DL	CONTRACT Kenn Addison
LINE 500E-#	STATION 240N	LOCATION FINLAYSON PELLY

## SAMPLE DESCRIPTION

COLOUR	GREY
TEXTURE	
SOIL TYPE	TILL
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	SAMPLER STARTED 9:15
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 9:30

## REMARKS:



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-2A1N #2	DRILL HOLE NO. 9	DATE 3 OCT 78
SAMPLE DEPTH 3.0	SAMPLERS MJB/DL	CONTRACT KERR ADDISON
LINE 500E	STATION 2A1N	LOCATION FINLAYSON PELLEY

## SAMPLE DESCRIPTION

COLOUR	GREY
TEXTURE	
SOIL TYPE	TILL
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED 9:30	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 10:25

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-241N #3 N/S	DRILL HOLE NO. 9	DATE 3 OCT 78
SAMPLE DEPTH 5m	SAMPLERS MSB/DL	CONTRACT KERR ADDISON
LINE 500E	STATION 241N	LOCATION FINLAYSON PELLEY

## SAMPLE DESCRIPTION

COLOUR	
TEXTURE	
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED 10:25	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 1:00

**REMARKS:** very hard ground. Required hydraulic jacks to remove rd pt. and sampler could not get small sampler open @ 5m

**BEMA INDUSTRIES LTD.**19790-88 Ave. R.R. 4  
Langley, B.C. V3A4P7 530-7772**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-270N #1	DRILL HOLE NO. 10	DATE 3 OCT 78
SAMPLE DEPTH 1.2 M	SAMPLERS MJB/DL	CONTRACT Kerr Addison
LINE 500E	STATION 270N	LOCATION FINLAYSON - PELLEY

**SAMPLE DESCRIPTION**

COLOUR	GREY
TEXTURE	GRAYELLY
SOIL TYPE	TILL
FRAGMENTS	
MINERALOXIDE	

**DRILLING TIME**

POINT STARTED 2:05	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 2:20

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-270N #2	DRILL HOLE NO. 10	DATE 3 OCT 78
SAMPLE DEPTH 2 M	SAMPLERS MSB/DL	CONTRACT KERR ADDISON
LINE 500E	STATION 270N	LOCATION FINLAYSON PELLEY

## SAMPLE DESCRIPTION

COLOUR	GREY
TEXTURE	GRAVELLY
SOIL TYPE	TILL
FRAGMENTS	SOME ORANGE SPECKS
MINERALOXIDE	

## DRILLING TIME

POINT STARTED 2:20	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 2:55

## REMARKS:

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-270N #3	DRILL HOLE NO. 10	DATE 3 OCT 78
SAMPLE DEPTH 3 M	SAMPLERS MSB/DL	CONTRACT KERR ADDISON
LINE 500E	STATION 270N	LOCATION FINLAYSON PELLEY

**SAMPLE DESCRIPTION**

COLOUR	Gray-Black
TEXTURE	Till
SOIL TYPE	
FRAGMENTS	YES.
MINERALOXIDE	

**DRILLING TIME**

POINT STARTED 2:55	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 3:20

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-270N #4	DRILL HOLE NO. 10	DATE 3 OCT 78
SAMPLE DEPTH 1 M	SAMPLERS MJB/DL	CONTRACT Kerr Addison
LINE 500E	STATION 270N	LOCATION FINLAYSON- PELLEY

## SAMPLE DESCRIPTION

COLOUR	GREY
TEXTURE	
SOIL TYPE	TILL
FRAGMENTS	ORANGE STREAKS
MINERALOXIDE	

## DRILLING TIME

POINT STARTED 3:20	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 430

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-300N #1	DRILL HOLE NO. 11	DATE 3 OCT 78
SAMPLE DEPTH 1 M	SAMPLERS MJB/DL	CONTRACT KERR ADDISON
LINE 500E	STATION 300N	LOCATION FINLAYSON PELLY

## SAMPLE DESCRIPTION

COLOUR	GREY-GREEN
TEXTURE	
SOIL TYPE	TILL
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	SAMPLER STARTED 4:45
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 5:00

## REMARKS:



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-300N #2	DRILL HOLE NO. 11	DATE 3 OCT 78
SAMPLE DEPTH 2 M	SAMPLERS MSB/DL	CONTRACT KERR. ADDISON
LINE 500E	STATION 300N	LOCATION FINLAYSON- PELWY

## SAMPLE DESCRIPTION

COLOUR	GREY-GREEN
TEXTURE	GRAVELLY
SOIL TYPE	TILL
FRAGMENTS	
MINERALOXIDE	FE STAINS

## DRILLING TIME

POINT STARTED	5:00	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	5:20

## REMARKS:



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-300N #3	DRILL HOLE NO. 11	DATE 3 OCT 78
SAMPLE DEPTH 3.0 m	SAMPLERS MSB/DL	CONTRACT KERR ADDISON
LINE 500E	STATION 300N	LOCATION FINLAYSON DELLY

## SAMPLE DESCRIPTION

COLOUR	Grey-Green - minor Blue
TEXTURE	clay.
SOIL TYPE	
FRAGMENTS	Yes. A.
MINERALOXIDE	

## DRILLING TIME

POINT STARTED 5:20	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 5:45

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-300N <del>#4</del> N.S.	DRILL HOLE NO. 11	DATE 3 OCT 78- 4 OCT
SAMPLE DEPTH 4 M	SAMPLERS MJB/DL	CONTRACT KERR ADDISON
LINE 500E	STATION 300N	LOCATION

## SAMPLE DESCRIPTION

COLOUR	
TEXTURE	
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	

**DRILLING TIME** 4. OCT 840-930

POINT STARTED 5:45	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED 6:45	SAMPLER EXTRACTED

**REMARKS:** NO SAMPLE. Lost Rd.  
POINT AT BOTTOM OF HOLE.



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-358N #1	DRILL HOLE NO. 12	DATE 4 OCT 78
SAMPLE DEPTH 1M	SAMPLERS MSB/DL	CONTRACT KERR ADDISON
LINE 500E	STATION 358N	LOCATION FINLAYSON PELLEY

## SAMPLE DESCRIPTION

COLOUR	GREY
TEXTURE	GRAVELLY FROZEN
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	9 30	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	9 50

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-358N #2	DRILL HOLE NO. 12	DATE 4 OCT 78
SAMPLE DEPTH 2 M	SAMPLERS MS BDL	CONTRACT KERR ADDISON
LINE 500E	STATION 358N	LOCATION FINLAYSON PELLEY

## SAMPLE DESCRIPTION

COLOUR	GREY-GREEN
TEXTURE	GRAVELLY
SOIL TYPE	TILL
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	9:50	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	10:15

## REMARKS:

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-358N #3	DRILL HOLE NO. 12	DATE 4 OCT 78
SAMPLE DEPTH 3 M	SAMPLERS MSB/DH.	CONTRACT KEAR ADDISON
LINE 500E	STATION 358N	LOCATION FINLAYSON PELLEY

**SAMPLE DESCRIPTION**

COLOUR	GREY - GREEN
TEXTURE	GRAVELLY
SOIL TYPE	TILL
FRAGMENTS	BROWN SPECKS
MINERALOXIDE	

**DRILLING TIME**

POINT STARTED	10:15	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	1040

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R. 4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500 E-358N #A	DRILL HOLE NO. 12	DATE 4 OCT 78
SAMPLE DEPTH 4 m	SAMPLERS MSB/DL DK	CONTRACT KERR ADDISON
LINE 500 E	STATION 358N	LOCATION FINLAYSON - PELTY

## SAMPLE DESCRIPTION

COLOUR	GREY - top
TEXTURE	GRAVELLY - top
SOIL TYPE	TILL - top      BEDROCK? Bottom
FRAGMENTS	Shale fragments
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	10:40	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	11:15

## REMARKS:



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 50DE-358N #5	DRILL HOLE NO. 12	DATE 40CT 78
SAMPLE DEPTH 4.9 M	SAMPLERS MSB. / DL. DK	CONTRACT Kerr Addison
LINE 50DE	STATION 358N	LOCATION FINLAYSON PELLEY

## SAMPLE DESCRIPTION

COLOUR	GREY - BROWN
TEXTURE	Weathered Bedrock + Till
SOIL TYPE	
FRAGMENTS	Some rounded frag. Some shale
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	11:15	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	12:05

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-332N #1	DRILL HOLE NO. 13	DATE 4 Oct 78
SAMPLE DEPTH 1 M	SAMPLERS MSB/DL DK	CONTRACT Kerr Addison
LINE 500E	STATION 332N	LOCATION Fairlayson - Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	12:45	SAMPLER STARTED	12:45
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	12:55

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-332N #2	DRILL HOLE NO. 13	DATE 4 Oct 78
SAMPLE DEPTH 2M	SAMPLERS MS B/DL DK	CONTRACT Kerr Addison
LINE 500E	STATION 332N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	12.55	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	1:25

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-332N #3	DRILL HOLE NO. 13	DATE 4 OCT 78
SAMPLE DEPTH 3.0	SAMPLERS MTB/DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 332N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey - Green till
TEXTURE	Gravelly
SOIL TYPE	
FRAGMENTS	YES
MINERALOXIDE	Fe Oxides around some tags.

## DRILLING TIME

POINT STARTED	1:25	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	2:00

## REMARKS:



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-332N # 4	DRILL HOLE NO. 13	DATE 4 OCT 78
SAMPLE DEPTH 4M	SAMPLERS MUS/DL/DK	CONTRACT Kent Addison
LINE 500E	STATION 332N	LOCATION FINAYSON - PELLEY

### SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	Yes
MINERALOXIDE	

### DRILLING TIME

POINT STARTED 2:00	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 2:45

**REMARKS:**

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R. 4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-332N #5	DRILL HOLE NO. 13	DATE 4 OCT 78
SAMPLE DEPTH 5.0	SAMPLERS MJB/DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 332N	LOCATION Finlayson Pelly

**SAMPLE DESCRIPTION**

COLOUR	Grey - Black
TEXTURE	Bedrock ?
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	Fe oxide

**DRILLING TIME**

POINT STARTED	2:15	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	3:25

**REMARKS:** Bottom blocked w. large frag. of shale? above till type material.



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-392N #1	DRILL HOLE NO. 1A	DATE 4 Oct 78
SAMPLE DEPTH 1 M	SAMPLERS MSB/DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 392N	LOCATION Finlayson pelly

## SAMPLE DESCRIPTION

COLOUR	Grey - Green
TEXTURE	
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	SAMPLER STARTED 3:30
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 3:45

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-392N # 2	DRILL HOLE NO. 14	DATE 4 OCT 78
SAMPLE DEPTH 2.0m	SAMPLERS MJB/DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 392N	LOCATION FINLAYSON - PELLEY

## SAMPLE DESCRIPTION

COLOUR	Gray-Green fill
TEXTURE	
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	Graphite frags.

## DRILLING TIME

POINT STARTED 3:45	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 4:10

## REMARKS:



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-392N # 3	DRILL HOLE NO. 14	DATE 4 Oct 78
SAMPLE DEPTH 3.0	SAMPLERS mJB/DL/DK	CONTRACT KERR ADDISON
LINE 500E	STATION 392N	LOCATION FINLAYSON PELLEY

## SAMPLE DESCRIPTION

COLOUR	Gray-Green
TEXTURE	Till
SOIL TYPE	
FRAGMENTS	Yes
MINERALOXIDE	limonite

## DRILLING TIME

POINT STARTED	4:10	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	4:30

## REMARKS:



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-392N # 4	DRILL HOLE NO. 14	DATE 4 OCT 78
SAMPLE DEPTH 4.0 m	SAMPLERS mJB/DL/DK	CONTRACT KERR ADDISON
LINE 500E	STATION 392N	LOCATION FINLAYSON PELLEY

## SAMPLE DESCRIPTION

COLOUR	Weathered Bedrock in
TEXTURE	bottom & clay till
SOIL TYPE	above.
FRAGMENTS	
MINERALOXIDE	Fe

## DRILLING TIME

POINT STARTED 4:30	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 5:45

## REMARKS:

Very difficult to extract - Hyd. Jack req'd



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-420N #1	DRILL HOLE NO. 15	DATE 5 Oct 78
SAMPLE DEPTH 1M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 420N	LOCATION Finlayson Belly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	orange stains limonite

## DRILLING TIME

POINT STARTED	SAMPLER STARTED 8:55
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 9:15

## REMARKS:

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-420N #2	DRILL HOLE NO. 15	DATE 5 Oct 78
SAMPLE DEPTH 2M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 420N	LOCATION Finlayson Pelly

**SAMPLE DESCRIPTION**

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Fill
FRAGMENTS	
MINERALOXIDE	orange specks limonite

**DRILLING TIME**

POINT STARTED 9:15	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 9:45

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-420N #3	DRILL HOLE NO. 15	DATE 5 Oct 78
SAMPLE DEPTH 3M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 420N	LOCATION Finlayson Belly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	orange stains limonite

## DRILLING TIME

POINT STARTED	9:45	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	10:20

**REMARKS:**

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E - 420N #A	DRILL HOLE NO. 15	DATE 5 OCT 78
SAMPLE DEPTH 4M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 420N	LOCATION Pelly Finlayson

**SAMPLE DESCRIPTION**

COLOUR	Grey-Green
TEXTURE	gravelly
SOIL TYPE	Till
FRAGMENTS	some shale frags.
MINERALOXIDE	orange stains limonite

**DRILLING TIME**

POINT STARTED	10:20	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	11:05

**REMARKS:**

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-420N #5	DRILL HOLE NO. 15	DATE 5 Oct 78
SAMPLE DEPTH 5 m	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 420N	LOCATION Finlayson Pelly

**SAMPLE DESCRIPTION**

COLOUR	Grey
TEXTURE	gravelly above, hard bedrock below
SOIL TYPE	fill above, bedrock below
FRAGMENTS	Visible <del>banding</del> banding
MINERAL OXIDE	orange & white streaks

**DRILLING TIME**

POINT STARTED 11:05	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 12:30

**REMARKS:** Reg'd Hyd. jack to extract round pt.



# BEMA INDUSTRIES LTD.

19790-88 Ave. R.R. 4  
Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-451N #1	DRILL HOLE NO. 16	DATE 5 OCT 78
SAMPLE DEPTH 1M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 451N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Brown
TEXTURE	frozen
SOIL TYPE	mwck
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	SAMPLER STARTED 11:30
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 145

## REMARKS:



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-451 N #2	DRILL HOLE NO. 16	DATE 5 Oct 78
SAMPLE DEPTH 2 m	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 451 N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	145	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	2:25

## REMARKS:



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-451N #3	DRILL HOLE NO. 16	DATE 5 Oct 78
SAMPLE DEPTH 3 m	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 451N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey - Green
TEXTURE	Gravelly
SOIL TYPE	fill
FRAGMENTS	
MINERALOXIDE	limonite

## DRILLING TIME

POINT STARTED 2:25	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 3:10

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-451N #4	DRILL HOLE NO. 16	DATE 5 Oct 78
SAMPLE DEPTH A M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 451N	LOCATION Finlayson - Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	limonite

## DRILLING TIME

POINT STARTED	3:10	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	4:15

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-451N #5	DRILL HOLE NO. 16	DATE 5 Oct 78
SAMPLE DEPTH 5M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 451N	LOCATION Finlayson pelly

## SAMPLE DESCRIPTION

COLOUR	Grey-green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	limonite, some white specks

## DRILLING TIME

POINT STARTED	4:15	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	5:30

## REMARKS:



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-451N #6	DRILL HOLE NO. 16	DATE 5 Oct 78
SAMPLE DEPTH 6m.	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 451N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	N/S
TEXTURE	
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	530	SAMPLER STARTED
POINT STOPPED		SAMPLER STOPPED
POINT EXTRACTED		SAMPLER EXTRACTED 6:35

**REMARKS:** Sampler jammed at bottom of hole & would not open



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R. 4

Langley, B.C. V3A4P7 530-7772

### OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-45IN #16	DRILL HOLE NO. 16	DATE 6 OCT 78
SAMPLE DEPTH 6m	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 45IN	LOCATION Pelly Finlayson

### SAMPLE DESCRIPTION

COLOUR	N/S
TEXTURE	
SOIL TYPE	
FRAGMENTS	
MINERALOXIDE	

### DRILLING TIME

POINT STARTED	8:25	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED	9:00	SAMPLER EXTRACTED	

### REMARKS:

~~Had~~ Bottom Rod  
sheared off when jacked  
up.



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E479N#1	DRILL HOLE NO. 17	DATE 6 OCT 78
SAMPLE DEPTH 1.2 m	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 479N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Brown
TEXTURE	frozen
SOIL TYPE	muck
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	<del>8:40</del>	SAMPLER STARTED	9:10
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	9:30

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-479N #2	DRILL HOLE NO. 17	DATE 6 OCT 78
SAMPLE DEPTH 2 M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 479N	LOCATION Pelly Finlayson

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	Limonite

## DRILLING TIME

POINT STARTED 9:30	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 9:55

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R. 4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-479N #3	DRILL HOLE NO. 17	DATE 6 OCT 78
SAMPLE DEPTH 3 M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 479N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	limonite

## DRILLING TIME

POINT STARTED	9:55	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	10:25

## REMARKS:



# BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 508E-479N#4	DRILL HOLE NO. 17	DATE 6 OCT 78
SAMPLE DEPTH A M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 508E	STATION 479 A/	LOCATION Emleyson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	white specks
MINERALOXIDE	limonite

## DRILLING TIME

POINT STARTED 10:25	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 12:15

**REMARKS:** Rod sheared off above round point. Had to drill new hole.

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-479N #5	DRILL HOLE NO. 17	DATE 6 OCT 78
SAMPLE DEPTH 5 M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 479N	LOCATION Fairbairn Pelly

**SAMPLE DESCRIPTION**

COLOUR	Black
TEXTURE	Gravelly Hard shale on
SOIL TYPE	fill bottom
FRAGMENTS	
MINERALOXIDE	

**DRILLING TIME**

POINT STARTED 12:15	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 1:00

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-509N #1	DRILL HOLE NO. 18	DATE 6 OCT 78
SAMPLE DEPTH 1.2 M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 509N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey-green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	SAMPLER STARTED 1:45
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 2:00

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R. 4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. S00E-509N #2	DRILL HOLE NO. 18	DATE 6 OCT 78
SAMPLE DEPTH 2 m	SAMPLERS DL DK	CONTRACT Kerr Addison
LINE S00E	STATION 509N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	Some shale
MINERALOXIDE	some limonite

## DRILLING TIME

POINT STARTED 2:00	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 2:20

**REMARKS:**

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-509N #3	DRILL HOLE NO. 18	DATE 6 OCT 78
SAMPLE DEPTH 3.1M	SAMPLERS DL DK	CONTRACT Kerr Addison
LINE 500E	STATION 509N	LOCATION Finlayson Pelly

**SAMPLE DESCRIPTION**

COLOUR	Black
TEXTURE	hard
SOIL TYPE	shale
FRAGMENTS	some weathered bedrock
MINERALOXIDE	limonite

**DRILLING TIME**

POINT STARTED	2:20	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	3:30

**REMARKS:** Sampler would not open  
Had to jack up + re sample.

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R. 4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-540N	DRILL HOLE NO. 19	DATE 6 OCT 78
SAMPLE DEPTH 1.8 M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 540N	LOCATION Finlayson Pelly

**SAMPLE DESCRIPTION**

COLOUR	Grey
TEXTURE	Gravelly
SOIL TYPE	Clay-Till
FRAGMENTS	
MINERALOXIDE	limonite

**DRILLING TIME**

POINT STARTED	SAMPLER STARTED 3:45
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 9:15

**REMARKS:** Could not get sample  
at 1m. - Too soft.



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-540N #2	DRILL HOLE NO. 19	DATE 6 Oct 78
SAMPLE DEPTH 3M	SAMPLERS DL/PK	CONTRACT Kerr Addison
LINE 500E	STATION 540N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	
SOIL TYPE	Clay-Till
FRAGMENTS	
MINERALOXIDE	some limonite

## DRILLING TIME

POINT STARTED	A: 15	SAMPLER STARTED
POINT STOPPED		SAMPLER STOPPED
POINT EXTRACTED		SAMPLER EXTRACTED 5:00

## REMARKS:

**BEMA INDUSTRIES LTD.**19790-88 Ave. R.R. 4  
Langley, B.C. V3A4P7 530-7772**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-540N #3	DRILL HOLE NO. 19	DATE 6 OCT 78
SAMPLE DEPTH 4 m	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 540N	LOCATION Finlayson Pelly

**SAMPLE DESCRIPTION**

COLOUR	Grey
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	some shale
MINERALOXIDE	

**DRILLING TIME**

POINT STARTED	5:00	SAMPLER STARTED
POINT STOPPED		SAMPLER STOPPED
POINT EXTRACTED		SAMPLER EXTRACTED 6:00

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R. 4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-540N #1	DRILL HOLE NO. 19	DATE 7 OCT 78
SAMPLE DEPTH 5.1M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 540N	LOCATION Finlayson Belly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Hard shale frags
SOIL TYPE	Till on bottom. some
FRAGMENTS	green coloring in shale.
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	8:30	SAMPLER STARTED
POINT STOPPED		SAMPLER STOPPED
POINT EXTRACTED		SAMPLER EXTRACTED 10:00

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E - 570N #1	DRILL HOLE NO. 20	DATE 7 OCT 78
SAMPLE DEPTH 1.1 m	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 570N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	grey-green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	limonite

## DRILLING TIME

POINT STARTED	SAMPLER STARTED 10:10
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 10:25

## REMARKS:



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-570N #2	DRILL HOLE NO. 20	DATE 7 Oct 78
SAMPLE DEPTH 2 m	SAMPLERS DL/DK	CONTRACT Kerr Addison.
LINE 500E	STATION 570N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	Some shale frags.
MINERAL OXIDE	limonite

## DRILLING TIME

POINT STARTED	10:25	SAMPLER STARTED
POINT STOPPED		SAMPLER STOPPED
POINT EXTRACTED		SAMPLER EXTRACTED 11:00

## REMARKS:

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-570N #3	DRILL HOLE NO. 20	DATE 7 OCT 78
SAMPLE DEPTH 3.2 M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 570N	LOCATION Finlayson Pelly

**SAMPLE DESCRIPTION**

COLOUR	Grey
TEXTURE	rocky
SOIL TYPE	Till
FRAGMENTS	lots of shale frags.
MINERALOXIDE	limonite

**DRILLING TIME**

POINT STARTED	11:00	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	11:35

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-570N #4	DRILL HOLE NO. 20	DATE 7 OCT 78
SAMPLE DEPTH 4 m	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 570N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Black
TEXTURE	fine gravelly, hard on bottom
SOIL TYPE	shale? graphite? ✓
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	11:35	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	2:15

**REMARKS:** lost sampler down hole  
Had to drill another hole. Very  
hard to extract sampler.



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-600N #1	DRILL HOLE NO. 21	DATE 7 OCT 78
SAMPLE DEPTH 1.1 M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 600E	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	limonite

## DRILLING TIME

POINT STARTED	2:30	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	2:58

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-600N #2	DRILL HOLE NO. 21	DATE 7 Oct 78
SAMPLE DEPTH 2 m	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 600N	LOCATION Einlayson Relly

## SAMPLE DESCRIPTION

COLOUR	Grey
TEXTURE	Gravelly
SOIL TYPE	Clay-Till
FRAGMENTS	
MINERALOXIDE	limonite

## DRILLING TIME

POINT STARTED	2:50	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	3:15

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-600N #3	DRILL HOLE NO. 21	DATE 7 OCT 78
SAMPLE DEPTH 3:1M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 600N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Fill-Clay
FRAGMENTS	Shale frags.
MINERALOXIDE	limonite

## DRILLING TIME

POINT STARTED 3:15	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 3:50

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4  
Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-600N #4	DRILL HOLE NO. 21	DATE 7 OCT 78
SAMPLE DEPTH 3.6M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 600N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey
TEXTURE	Gravelly
SOIL TYPE	clay-till - weathered bedrock
FRAGMENTS	
MINERALOXIDE	limonite

## DRILLING TIME

POINT STARTED	350	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	4.25

**REMARKS:** Drill would go no further  
- very hard ground.



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R. 4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-630N #1	DRILL HOLE NO. 22	DATE 7 OCT 78
SAMPLE DEPTH 1 M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 630N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey
TEXTURE	soft, fine gravelly
SOIL TYPE	clay
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	4:40	SAMPLER STARTED	4:40
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	4:55

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-630N #2	DRILL HOLE NO. 22	DATE 7 Oct 78
SAMPLE DEPTH 2 M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 630N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	limonite

## DRILLING TIME

POINT STARTED	4:55	SAMPLER STARTED
POINT STOPPED		SAMPLER STOPPED
POINT EXTRACTED		SAMPLER EXTRACTED 5:15

**REMARKS:**

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-630N #3	DRILL HOLE NO. 22	DATE 7 OCT 78
SAMPLE DEPTH 3.1M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 630N	LOCATION Finlayson Pelly

**SAMPLE DESCRIPTION**

COLOUR	Grey
TEXTURE	fine Grained
SOIL TYPE	Clay-Till Hard shale on Bottom
FRAGMENTS	
MINERALOXIDE	some limonite

**DRILLING TIME**

POINT STARTED	5:15	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	5:50

**REMARKS:**

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-660N #1	DRILL HOLE NO. 23	DATE 8 OCT 78
SAMPLE DEPTH 1.2 M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 660N	LOCATION Finlayson Pelly

**SAMPLE DESCRIPTION**

COLOUR	Grey
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	Quartz frags.
MINERALOXIDE	

**DRILLING TIME**

POINT STARTED	SAMPLER STARTED 8:25
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 8:45

**REMARKS:**

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500 E - 660 N #2	DRILL HOLE NO. 23	DATE 8 OCT 78
SAMPLE DEPTH 2 M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500 E	STATION 660 N	LOCATION Finbyson Pelly

**SAMPLE DESCRIPTION**

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	some limonite

**DRILLING TIME**

POINT STARTED 8:45	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 9:05

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-660N #3	DRILL HOLE NO. 23	DATE 8 Oct 78
SAMPLE DEPTH 3.1	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 660N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	limonite

## DRILLING TIME

POINT STARTED 9:05	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 9:35

**REMARKS:**



BEMA INDUSTRIES LTD.

19790-88 Ave. R.R. 4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-660N #4	DRILL HOLE NO. 23	DATE 8 Oct 78
SAMPLE DEPTH 4 m	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 660N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey - Green
TEXTURE	Dense - soft.
SOIL TYPE	clay
FRAGMENTS	some pebbles
MINERALOXIDE	

## DRILLING TIME

POINT STARTED 9:35	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 10:40

**REMARKS:** Very hard drilling. Could go no further.



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-700N #1	DRILL HOLE NO. 2A	DATE 30 OCT 78
SAMPLE DEPTH 1M	SAMPLERS DK/DK	CONTRACT Kerr Addison
LINE 500E	STATION 700N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey-Green
TEXTURE	Gravelly
SOIL TYPE	Till
FRAGMENTS	
MINERALOXIDE	

## DRILLING TIME

POINT STARTED	SAMPLER STARTED 11:00
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 11:25

**REMARKS:**

**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R. 4

Langley, B.C. V3A4P7 530-7772

**OVERBURDEN DRILLING LOG**

SAMPLE NO. 500E-700N #2	DRILL HOLE NO. 24	DATE 8 OCT 78
SAMPLE DEPTH 2 m	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 700N	LOCATION Finlayson Belly

**SAMPLE DESCRIPTION**

COLOUR	Grey
TEXTURE	
SOIL TYPE	Clay-Till
FRAGMENTS	some shale frags.
MINERALOXIDE	limonite

**DRILLING TIME**

POINT STARTED 11:25	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 11:50

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-700N #3	DRILL HOLE NO. 24	DATE 8 OCT 78
SAMPLE DEPTH 3 M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 700N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey
TEXTURE	Dense - fine gravelly
SOIL TYPE	Clay - Till
FRAGMENTS	
MINERALOXIDE	limonite

## DRILLING TIME

POINT STARTED	11:50	SAMPLER STARTED	
POINT STOPPED		SAMPLER STOPPED	
POINT EXTRACTED		SAMPLER EXTRACTED	12:25

**REMARKS:**



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-700N #4	DRILL HOLE NO. 2A	DATE 8 OCT 78
SAMPLE DEPTH 4M	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 700N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Grey
TEXTURE	fine gravelly
SOIL TYPE	clay-till
FRAGMENTS	soft white rock frags
MINERALOXIDE	limonite

## DRILLING TIME

POINT STARTED	12:25	SAMPLER STARTED
POINT STOPPED		SAMPLER STOPPED
POINT EXTRACTED		SAMPLER EXTRACTED 1:20

## REMARKS:



**BEMA INDUSTRIES LTD.**

19790-88 Ave. R.R.4

Langley, B.C. V3A4P7 530-7772

## OVERBURDEN DRILLING LOG

SAMPLE NO. 500E-700N #5	DRILL HOLE NO. 24	DATE 8 OCT 78
SAMPLE DEPTH 5m.	SAMPLERS DL/DK	CONTRACT Kerr Addison
LINE 500E	STATION 700N	LOCATION Finlayson Pelly

## SAMPLE DESCRIPTION

COLOUR	Black
TEXTURE	Dense - Gravelly
SOIL TYPE	Clay-Till
FRAGMENTS	
MINERALOXIDE	some limonite

## DRILLING TIME

POINT STARTED 1:40	SAMPLER STARTED
POINT STOPPED	SAMPLER STOPPED
POINT EXTRACTED	SAMPLER EXTRACTED 2:35

**REMARKS:**