


Faro Mine
Env. Water
Quality Zone 2
Pit Water

(Thousands)

007491



DATE	DEPTH (m)	STATIC W.L. (m)	feet
09-MAY-89	47.50	1152.63	3781.6
07-JUN-89	46.18	1153.95	3785.9
26-JUL-89	44.74	1155.39	3790.6
30-AUG-89	43.01	1157.12	3796.3
17-OCT-89	42.39	* 1157.74	3798.4
28-NOV-89	42.27	1157.86	3798.8
14-DEC-89	42.26	1157.87	3798.8
31-JAN-90	42.25	1157.88	3798.8
23-FEB-90	42.26	1157.87	3798.8

→ compared to 3800 base level of overflow pipe.

and 3810 level of Valve.

Pumping range 3802-3805

ZONE II DEEP WELL

Co-ordinates: 5689N/15325E

Elevation: 3935.43' (mine elev.) (1199.52 meters)
 Pipe elev: 2' higher (1200.13 meters - conservative datum elevation)
 Siphon Discharge: +/- 3802' (mine elev.) (+/- 1158.85 meters)


DATE	DEPTH	STATIC	REL. TO	TEMP.	pH	ALKAL.	AMMONIA	COPPER	LEAD	ZINC	MANGANE	IRON	SODIUM	SULFATE
	(m)	M.L. (a)	SIPHON (m)	(C)		(mg/L)	(mg/L)	(mg/L)	(mg/L)	(mg/L)	(mg/L)	(mg/L)	(mg/L)	(mg/L)
09-MAY-89	47.50	1152.63	-6.22											
07-JUN-89	46.18	1153.99	-5.90											
26-JUL-89	44.74	1155.39	-3.46											
30-AUG-89	43.01	1157.11	-1.73											
17-OCT-89	42.39	1157.74	-1.11											
28-NOV-89	42.27	1157.86	-0.99											
14-DEC-89	42.26	1157.87	-0.98											
31-JAN-90	42.25	1157.88	-0.97											
23-FEB-90	42.26	1157.87	-0.98											
21-MAR-90	42.26	1157.87	-0.98											

SENT BY: Curragh Resources, Inc. : 9-20-90 : 3:49PM : Faro Mine - CURRAGH Whitehorse # 9

WATER LEVEL (m)
(Thousands)

ZONE II DEEP WELL

Static Water Level



□ STATIC W.L. (m)