


# FIGURE 3

## SEEPAGE FROM CROSS VALLEY DAM



□ X11

+ X12

◇ X13


1989  
— EFFLUENT LIMIT

007532

Faro Mine  
Environment  
Water Quality

FIGURE 14 : AMMONIA USEAGE


MINE CONSUMPTION



1989

# FIGURE 12 : CYANIDE (WAD)

AVERAGE MONTHLY CONCENTRATION



# FIGURE 24 : CYANIDE (TOTAL)

AVERAGE MONTHLY CONCENTRATION

