


F-150
 K-section - 121+000 (Sheet 213)
 Geological Interpretation (GVI)
 1" = 50'
 Jan/86 (A.S.T.)



One type and amount of ID4/ZL uncertain in this area between 75-12 & 75-10 due to faulting.

LEGEND

- Fault (inferred) with relative movement.
- Fault (assumed) with relative movement.
- Lithologic Contact (defined).
- Lithologic Contact (inferred).
- Lithologic Contact (assumed).
- Contact of sericite/white mica alteration with host rock.
- Piercing point of osh through section.
- Lithologic Contacts above pit surface.

GEOLOGICAL INTERPRETATION (ANVIL CODES)

INTERPRETED BY	DATE	DRAWN BY	DATE	PLAT. RATIO	1" = 50' UNITS: FEET	CYPRUS ANVIL MINING CORPORATION
R. S. T.	JAN. 1986	T. M.	JAN. 1986			THE IMPERIAL ANVIL
						VERTICAL CROSS SECTION 121+000
						315 DEG VIEW AZIMUTH 45 DEG PROFILE

INTERPRETED BY	DATE	DRAWN BY	DATE	PLAT. RATIO	1" = 50' UNITS: FEET	CYPRUS ANVIL MINING CORPORATION
R. S. T.	JAN. 1986	T. M.	JAN. 1986			THE IMPERIAL ANVIL
						VERTICAL CROSS SECTION 121+000
						315 DEG VIEW AZIMUTH 45 DEG PROFILE

010805

10/1/86 210-56