


WELL 90DY05  
DEPTH 281  
PICTURE No.  
INCLINATION 1.71  
OBS. DIR. W345  
COR. DIR. 345  
TOOL FACE  
RUN BY J. 26/100  
DATE Oct 29/90  
CHECKED BY


SPERRY-SUN

019222





WELL 90DY05  
DEPTH 721  
PICTURE No.  
INCLINATION  
OBS. DIR.  
COR. DIR.  
TOOL FACE  
RUN BY J. 26/100  
DATE Oct 29/90  
CHECKED BY

SPERRY-SUN




WELL 90DY05  
DEPTH 921  
PICTURE No.  
INCLINATION 3.0  
OBS. DIR. W301  
COR. DIR. 301  
TOOL FACE  
RUN BY J. 26/100  
DATE Oct 29/90  
CHECKED BY

SPERRY-SUN





WELL 90DY05  
DEPTH 821  
PICTURE No.  
INCLINATION 1.2  
OBS. DIR. W345  
COR. DIR. 345  
TOOL FACE  
RUN BY J. 26/100  
DATE Oct 29/90  
CHECKED BY

SPERRY-SUN




WELL 90DY05  
DEPTH 501  
PICTURE No.  
INCLINATION 2.2  
OBS. DIR. W37 N  
COR. DIR. 354  
TOOL FACE  
RUN BY J. 26/100  
DATE Oct 29/90  
CHECKED BY

SPERRY-SUN



WELL 90DY05  
DEPTH 121  
PICTURE No.  
INCLINATION 1.23  
OBS. DIR. W835  
COR. DIR. 303  
TOOL FACE  
RUN BY J. 26/100  
DATE Oct 29/90  
CHECKED BY

SPERRY-SUN



WELL 90DY05  
DEPTH 1221  
PICTURE No.  
INCLINATION  
OBS. DIR.  
COR. DIR.  
TOOL FACE  
RUN BY J. 26/100  
DATE Oct 29/90  
CHECKED BY

SPERRY-SUN

