


TABLE 5 DATA FOR SPECIFIC WATER QUALITY PARAMETERS UPSTREAM OF THE FRESHWATER POND IN ROSE CREEK

PARAMETER	LOCATION (DATE)				
	ROSE CREEK ABOVE ROAD CROSSING (AUG 18/80)	ROAD CROSSING (MAY 30/80)	(JULY 3/80)	ROSE CREEK ABOVE FRESHWATER POND (MAY 30/80)	FRESHWATER POND (JULY 3/80)
pH	7.4	7.42	7.5	7.48	7.68
Zinc (Zn) mg/l	0.13	0.21	0.004	0.014	0.009
Lead (Pb) mg/l	0.15	0.002	0.005	0.026	0.004
Copper (Cu) mg/l	0.03	0.002	0.003	0.003	0.004
Source	Weagle (1980)	CAMC	CAMC	CAMC	CAMC

Analysis for Weagle (1980) done by Cyprus Anvil Mining Corp., Faro.

CAMC Analysis done by Chemex, Vancouver, B.C.



**FIGURE 1. Details of study area.**

- - Beaver Dam
- △ - Intensive Sampling
- |a| --- - Habitat Boundary
- x - Spot Check

<b>SCALE:</b> 1:50,000	<b>APPROVED BY:</b>	<b>DRAWN BY:</b>
<b>DATE:</b>		<b>REVISED:</b>
		<b>DRAWING NUMBER:</b>