

WELL V-1-R
DEPTH 145
PICTURE NO. _____
INCLINATION 4°
OBS. DIR. N 43° W
COR. DIR. 350° az
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun

101-7-06-(9/76)250M

WELL V-1-R
DEPTH 145
PICTURE NO. _____
INCLINATION 4°
OBS. DIR. N 45° W
COR. DIR. 348° az
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun

101-7-06-(9/76)250M

WELL V-1-R
DEPTH 345
PICTURE NO. _____
INCLINATION 7°
OBS. DIR. N 78° W
COR. DIR. 315° az
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun

101-7-06-(9/76)250M

WELL V-1-R
DEPTH 248
PICTURE NO. _____
INCLINATION 16.5
OBS. DIR. N 85° W
COR. DIR. 308°
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun

101-7-06-(9/76)250M



020621