

WELL V-60-R
DEPTH 474
PICTURE NO. _____
INCLINATION 9°
OBS. DIR. _____
COR. DIR. _____
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun

101-7-06-(9/76)250M

WELL V-60-R
DEPTH 374
PICTURE NO. _____
INCLINATION 5.5°
OBS. DIR. N63 E
COR. DIR. 096°02
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun

101-7-06-(9/76)250M

WELL V-60-R
DEPTH 274
PICTURE NO. _____
INCLINATION 2°
OBS. DIR. N40 E
COR. DIR. 073°02
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun


101-7-06-(9/76)250M

WELL V-60-R
DEPTH 174
PICTURE NO. _____
INCLINATION 1.5°
OBS. DIR. N65°E
COR. DIR. 098°02
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun

101-7-06-(9/76)250M



020623