

WELL V-28-R
DEPTH 118
PICTURE NO. 4
INCLINATION 5.5°
OBS. DIR. N60°W
COR. DIR. 333° 22
TOOL FACE
RUN BY Bill
DATE Aug. 18
CHECKED BY DJH



sperry-sun

101-7-06-(9/76)250M

WELL V-28-R
DEPTH 218
PICTURE NO. 3
INCLINATION 7.3
OBS. DIR. N74W
COR. DIR. 319° 22
TOOL FACE
RUN BY Bill
DATE Aug. 18
CHECKED BY DJH



sperry-sun

101-7-06-(9/76)250M

WELL V-28-R
DEPTH 318
PICTURE NO. 2
INCLINATION 12°
OBS. DIR. N83W
COR. DIR. 310° 22
TOOL FACE
RUN BY Bill
DATE Aug. 18
CHECKED BY DJH



sperry-sun

101-7-06-(9/76)250M

WELL V-28-R
DEPTH 418
PICTURE NO. 1
INCLINATION 17°
OBS. DIR. N73W
COR. DIR. 320°
TOOL FACE
RUN BY Bill
DATE Aug. 18
CHECKED BY DJH



sperry-sun

101-7-06-(9/76)250M

020630