

WELL V 318
DEPTH 449
PICTURE NO. _____
INCLINATION 7°
OBS. DIR. N 20° E
COR. DIR. 53° Az
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun

101-7-06-(9/76)250M

WELL V 318
DEPTH 349
PICTURE NO. _____
INCLINATION 2°
OBS. DIR. N 40° E
COR. DIR. 73° Az
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun

101-7-06-(9/76)250M

WELL V 318
DEPTH 249
PICTURE NO. _____
INCLINATION 2°
OBS. DIR. N 38° E
COR. DIR. 71° Az
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun


101-7-06-(9/76)250M

WELL V 318
DEPTH 149
PICTURE NO. _____
INCLINATION 8 1/2°
OBS. DIR. N 40° E
COR. DIR. 73° Az
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun

101-7-06-(9/76)250M



020633