


WELL V-30-R
DEPTH 115'
PICTURE NO. _____
INCLINATION 4.2°
OBS. DIR. N70E
COR. DIR. 10.3°
TOOL FACE _____
RUN BY AKM
DATE AUG 12/79
CHECKED BY DJH



sperry-sun

101-7-06-(9/76)250M




WELL V-30-R
DEPTH 215'
PICTURE NO. _____
INCLINATION 2.8°
OBS. DIR. N90°E
COR. DIR. 123° 02'
TOOL FACE _____
RUN BY KM
DATE AUG. 12/79
CHECKED BY DJH



sperry-sun

101-7-06-(9/76)250M



WELL V-30-R
DEPTH 315'
PICTURE NO. _____
INCLINATION 2.8°
OBS. DIR. N36E
COR. DIR. 069° 02'
TOOL FACE _____
RUN BY KM
DATE AUG. 12/79
CHECKED BY DJH



sperry-sun

101-7-06-(9/76)250M



WELL V-30-R
DEPTH 415'
PICTURE NO. _____
INCLINATION 3.5°
OBS. DIR. N30W
COR. DIR. 003° 02'
TOOL FACE _____
RUN BY KM
DATE AUG. 12/79
CHECKED BY DJH



sperry-sun

101-7-06-(9/76)250M



020635