

WELL V-126-R
DEPTH 520
PICTURE NO. _____
INCLINATION 14.5°
OBS. DIR. N 35° W
COR. DIR. 358°
TOOL FACE _____
RUN BY DJH
DATE June 3/79
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V-126-R
DEPTH 420
PICTURE NO. _____
INCLINATION 10.5°
OBS. DIR. N 03° W
COR. DIR. 030°
TOOL FACE _____
RUN BY DJH
DATE June 3/79
CHECKED BY _____

PO?



sperry-sun

SP-132 (11-74)

WELL V-126-R
DEPTH 270
PICTURE NO. _____
INCLINATION 4°
OBS. DIR. S 22° E
COR. DIR. 191°
TOOL FACE _____
RUN BY DJH
DATE June 3/79
CHECKED BY _____



sperry-sun





SP-132 (11-74)

WELL V-126-R
DEPTH 1130
PICTURE NO. _____
INCLINATION 3°
OBS. DIR. N 84° E
COR. DIR. 117°
TOOL FACE _____
RUN BY DJH
DATE June 3
CHECKED BY _____



sperry-sun

SP-132 (11-74)



020637