

WELL V-101-R
DEPTH 207
PICTURE NO. 4
INCLINATION 4.25
OBS. DIR. S 57.3 W
COR. DIR. 320°
TOOL FACE _____
RUN BY DJH
DATE _____
CHECKED BY _____



sperry-sun
SP-132 (11-74)

WELL V-101-R
DEPTH 107
PICTURE NO. 5
INCLINATION 2°
OBS. DIR. N 88 W
COR. DIR. 305°
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun
SP-132 (11-74)

WELL V-101-R
DEPTH 407
PICTURE NO. 2
INCLINATION 1.35
OBS. DIR. S 50 W
COR. DIR. 263°
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun
SP-132 (11-74)

WELL V-101-R
DEPTH 307
PICTURE NO. 3
INCLINATION 5°
OBS. DIR. N 80 W
COR. DIR. 313°
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____







sperry-sun
SP-132 (11-74)

WELL V-101-R
DEPTH 507
PICTURE NO. 1
INCLINATION 2°
OBS. DIR. S 10 W
COR. DIR. 223° 02'
TOOL FACE _____
RUN BY _____
DATE _____
CHECKED BY _____



sperry-sun
SP-132 (11-74)



020640