

WELL VII9R
DEPTH 391
PICTURE NO. 1
INCLINATION 304.4°
OBS. DIR. N 25° ?
COR. DIR. 058
TOOL FACE
RUN BY AL
DATE JUNE 21
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL VII9R
DEPTH 291
PICTURE NO. 2
INCLINATION 3.50
OBS. DIR. N 28° 05
COR. DIR. 061 45°
TOOL FACE
RUN BY AL
DATE JUNE 21
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL VII9R
DEPTH 191
PICTURE NO. 3
INCLINATION 1.80
OBS. DIR. N
COR. DIR. 33°
TOOL FACE
RUN BY AL
DATE JUNE 21
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL VII9R
DEPTH 21
PICTURE NO. 4
INCLINATION 10
OBS. DIR. N
COR. DIR. 033°
TOOL FACE
RUN BY AL
DATE JUNE 21
CHECKED BY _____



sperry-sun

SP-132 (11-74)



020641