

WELL V-110-R
DEPTH 193
PICTURE NO. _____
INCLINATION 2.25°
OBS. DIR. N72°W
COR. DIR. 321° 02'
TOOL FACE _____
RUN BY _____
DATE June 17
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V-110-R
DEPTH 213
PICTURE NO. _____
INCLINATION 2°
OBS. DIR. N78°W
COR. DIR. 323°
TOOL FACE _____
RUN BY DJH
DATE _____
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V-110-R
DEPTH 333
PICTURE NO. _____
INCLINATION 4.5°
OBS. DIR. N66°E
COR. DIR. 099°
TOOL FACE _____
RUN BY _____
DATE June 17
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V-110-R
DEPTH 413
PICTURE NO. _____
INCLINATION 9.25°
OBS. DIR. N60°E
COR. DIR. 093°
TOOL FACE _____
RUN BY _____
DATE June 17 / 79
CHECKED BY _____



sperry-sun






SP-132 (11-74)

WELL V-110-R
DEPTH 533
PICTURE NO. _____
INCLINATION 12°
OBS. DIR. N54°E
COR. DIR. 087°
TOOL FACE _____
RUN BY DJH
DATE June 17 / 79
CHECKED BY _____



sperry-sun

SP-132 (11-74)



020644