

WELL V 71 R
DEPTH 38'
PICTURE NO. 4
INCLINATION 2.2°
OBS. DIR. N 48° W
COR. DIR. 345°
TOOL FACE AL
RUN BY AL
DATE JUL 6
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V 71 R
DEPTH 118'
PICTURE NO. 3
INCLINATION 2.2°
OBS. DIR. N 43° E
COR. DIR. 076°
TOOL FACE AL
RUN BY AL
DATE JUL 6
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V 71 R
DEPTH 253'
PICTURE NO. 2
INCLINATION 2.6°
OBS. DIR. N 17° E
COR. DIR. 050°
TOOL FACE AL
RUN BY AL
DATE JUL 6
CHECKED BY _____



sperry-sun


SP-132 (11-74)

WELL V 71 R
DEPTH 393'
PICTURE NO. 1
INCLINATION 8.3°
OBS. DIR. N 21° E
COR. DIR. 084°
TOOL FACE AL
RUN BY AL
DATE JUL 6
CHECKED BY _____



sperry-sun

SP-132 (11-74)



020645