

WELL V-45-R
DEPTH 489
PICTURE NO. 7 1/2°
INCLINATION N 42° E
OBS. DIR. 75° Az
COR. DIR. 75° Az
TOOL FACE
RUN BY
DATE
CHECKED BY



sperry-sun

101-7-06-(9/76)250M

WELL V-45-R
DEPTH 389
PICTURE NO. 10
INCLINATION 40
OBS. DIR. N 35° E
COR. DIR. 68° Az
TOOL FACE
RUN BY
DATE
CHECKED BY



sperry-sun

101-7-06-(9/76)250M

WELL V-45-R
DEPTH 289
PICTURE NO. 30
INCLINATION 70°
OBS. DIR. N 70° E
COR. DIR. 40° Az
TOOL FACE
RUN BY
DATE
CHECKED BY



sperry-sun

101-7-06-(9/76)250M

WELL V-45-R
DEPTH 189
PICTURE NO. 20
INCLINATION N 15° W
OBS. DIR. 18° Az
COR. DIR. 18° Az
TOOL FACE
RUN BY
DATE
CHECKED BY



sperry-sun

101-7-06-(9/76)250M

WELL V-45-R
DEPTH 689
PICTURE NO. 120
INCLINATION N 25° E
OBS. DIR. 58° Az
COR. DIR. 58° Az
TOOL FACE
RUN BY
DATE
CHECKED BY



sperry-sun

101-7-06-(9/76)250M

WELL V-45-R
DEPTH 589
PICTURE NO. 90
INCLINATION N 52° E
OBS. DIR. 85° Az
COR. DIR. 85° Az
TOOL FACE
RUN BY
DATE
CHECKED BY



sperry-sun

101-7-06-(9/76)250M

020647