

WELL V-117-R
DEPTH 419
PICTURE NO. 1
INCLINATION 4°
OBS. DIR. S 45° E
COR. DIR. 168° az
TOOL FACE
RUN BY Bill
DATE Aug. 18
CHECKED BY _____



sperry-sun

101-7-06-(9/76)250M

WELL V-117-R
DEPTH 269
PICTURE NO. 2
INCLINATION 1.5
OBS. DIR. N 40° W
COR. DIR. 353° az
TOOL FACE
RUN BY Bill
DATE Aug 18
CHECKED BY _____



sperry-sun


101-7-06-(9/76)250M

WELL V-117-R
DEPTH 119
PICTURE NO. 3
INCLINATION 5.5
OBS. DIR. N 10° W
COR. DIR. 023° az
TOOL FACE
RUN BY Bill
DATE Aug. 18
CHECKED BY _____



sperry-sun

101-7-06-(9/76)250M



020648