

WELL V 72 R
 DEPTH 211'
 PICTURE NO. 3
 INCLINATION 2.4°
 OBS. DIR. N 110° E
 COR. DIR. 44°
 TOOL FACE _____
 RUN BY AL
 DATE JULY 11
 CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V 72 R
 DEPTH 311'
 PICTURE NO. 2
 INCLINATION 5.5°
 OBS. DIR. N 160° E
 COR. DIR. 49°
 TOOL FACE _____
 RUN BY AL
 DATE JULY 11
 CHECKED BY _____



sperry-sun




SP-132 (11-74)

WELL V 72 R
 DEPTH 411'
 PICTURE NO. 4
 INCLINATION 7.8°
 OBS. DIR. N 50° E
 COR. DIR. 83°
 TOOL FACE _____
 RUN BY AL
 DATE JULY 11
 CHECKED BY _____



sperry-sun

SP-132 (11-74)



020650