

WELL V 84 R
DEPTH 418
PICTURE NO. 2
INCLINATION 7.4°
OBS. DIR. N 41° E
COR. DIR. 74°
TOOL FACE _____
RUN BY AL
DATE JUNE 28
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V 84 R
DEPTH 318
PICTURE NO. 3
INCLINATION 6.8°
OBS. DIR. N 39° E
COR. DIR. 72°
TOOL FACE _____
RUN BY AL
DATE JUNE 28
CHECKED BY _____



sperry-sun

SP-132 (11-74)

WELL V 84 R
DEPTH 68'
PICTURE NO. 3
INCLINATION N 15° E
OBS. DIR. 150°
COR. DIR. _____
TOOL FACE _____
RUN BY AL
DATE JUNE 28
CHECKED BY _____

N 17° E

050



sperry-sun

SP-132 (11-74)

WELL V 84 R
DEPTH 488'
PICTURE NO. 1
INCLINATION 3.9°
OBS. DIR. N 48° E
COR. DIR. 81°
TOOL FACE _____
RUN BY AL
DATE JUNE 28
CHECKED BY _____



sperry-sun

SP-132 (11-74)

020651