

Compass N. Good?

WELL 88X-02

DEPTH 528'

PICTURE NO. 10F1

INCLINATION 12°?

OBS. DIR. ~~N 50° E~~ S 17° E

COR. DIR. 139°

TOOL FACE _____

RUN BY CVR

DATE March 17

CHECKED BY S. Cheusman



sperry-sun



020659