


WELL X88-01
DEPTH 629
PICTURE NO. 1
INCLINATION 20°
OBS. DIR. N5°W
COR. DIR. 027
TOOL FACE _____
RUN BY CUP
DATE March 14 / 88
CHECKED BY _____



sperry-sun



0206660