

WELL 88G-01
DEPTH 283'
PICTURE NO. 1
INCLINATION ~~90~~ 178.5
OBS. DIR. N33 E
COR. DIR. 064
TOOL FACE _____
RUN BY CVR
DATE 21, 10/80
CHECKED BY _____



sperry-sun



020663