


WELL 886-04
DEPTH 319
PICTURE NO. 1 of 2
INCLINATION ~~290~~ 177.0
OBS. DIR. N44W
COR. DIR. 348
TOOL FACE _____
RUN BY CKR
DATE JULY 22/88
CHECKED BY _____



sperry-sun



WELL 886-04
DEPTH 219
PICTURE NO. 2 of 2
INCLINATION ~~290~~ 177.5
OBS. DIR. N42W
COR. DIR. 350
TOOL FACE _____
RUN BY CKR
DATE JULY 22/88
CHECKED BY _____



sperry-sun



020664