

WELL B8VX-01  
DEPTH 483  
PICTURE NO. 2 of 3  
INCLINATION 171.9  
OBS. DIR. N48°E  
COR. DIR. \_\_\_\_\_  
TOOL FACE \_\_\_\_\_  
RUN BY CVR  
DATE AUG 22 / 88  
CHECKED BY \_\_\_\_\_



sperry-sun

WELL B8VX-01  
DEPTH 683'  
PICTURE NO. 1 of 3  
INCLINATION \_\_\_\_\_  
OBS. DIR. N28°E  
COR. DIR. 059  
TOOL FACE 166.8  
RUN BY CVR  
DATE AUG 22 / 88  
CHECKED BY \_\_\_\_\_



sperry-sun

WELL B8VX-01  
DEPTH 283'  
PICTURE NO. 3 of 3  
INCLINATION 175.8  
OBS. DIR. N51°E  
COR. DIR. 082  
TOOL FACE \_\_\_\_\_  
RUN BY CVR  
DATE AUG 22 / 88 2:30AM  
CHECKED BY \_\_\_\_\_



sperry-sun

020665