

WELL 88V-04
DEPTH 222'
PICTURE NO. 2 of 2
INCLINATION 179.25
OBS. DIR. S 3° W
COR. DIR. 215°
TOOL FACE _____
RUN BY CVR
DATE June 18
CHECKED BY _____




sperry-sun

WELL 88V-04
DEPTH 332'
PICTURE NO. 1 of 2
INCLINATION 172°
OBS. DIR. S 8° E
COR. DIR. _____
TOOL FACE _____
RUN BY CVR
DATE _____
CHECKED BY _____



sperry-sun



020666