


WELL 88V-02
DEPTH 242
PICTURE NO. 1
INCLINATION -82° -82.2°
OBS. DIR. S 12° W
COR. DIR. 150°
TOOL FACE _____
RUN BY CVR
DATE _____
CHECKED BY _____




sperry-sun



WELL 88V-02
DEPTH 142
PICTURE NO. 2
INCLINATION 90 - 81°
OBS. DIR. E 9° S
COR. DIR. 131°
TOOL FACE _____
RUN BY CVR
DATE _____
CHECKED BY _____



sperry-sun



020668