

WELL 88V-06
DEPTH 279'
PICTURE NO. 1
INCLINATION - 88.5
OBS. DIR. S 64° E
COR. DIR. 148°
TOOL FACE _____
RUN BY CVR
DATE JUNE 19/88
CHECKED BY _____



sperry-sun



020669