

WELL 88VX-02
DEPTH 215
PICTURE NO. 3 of 3
INCLINATION ~~180~~ 178.2
OBS. DIR. N10°W
COR. DIR. 032
TOOL FACE
RUN BY CVR
DATE AUG 26/88
CHECKED BY _____



sperry-sun

WELL 88VX-02
DEPTH 415
PICTURE NO. 2 of 3
INCLINATION 173.5
OBS. DIR. N33°E
COR. DIR. 065°
TOOL FACE
RUN BY CVR
DATE AUG 26/88
CHECKED BY _____



sperry-sun

WELL 88VX-02
DEPTH 615
PICTURE NO. 1 of 3
INCLINATION 170°
OBS. DIR. N48°E
COR. DIR. 080
TOOL FACE
RUN BY CVR
DATE AUG 26/88
CHECKED BY _____



sperry-sun

020672