


WELL 88VX-03
DEPTH 490'
PICTURE NO. 1
INCLINATION 171.5
OBS. DIR. N4°E
COR. DIR. 036
TOOL FACE _____
RUN BY CVR
DATE AUG 28/88
CHECKED BY _____



sperry-sun



WELL 88VX-03
DEPTH 390'
PICTURE NO. 2
INCLINATION 174.5
OBS. DIR. N4°W
COR. DIR. 028
TOOL FACE _____
RUN BY CVR
DATE AUG 28/88
CHECKED BY _____




sperry-sun



WELL 88VX-03
DEPTH 190'
PICTURE NO. 3 of 3
INCLINATION 176.2
OBS. DIR. N22E
COR. DIR. 054°
TOOL FACE 60
RUN BY AUG 28/88
DATE _____
CHECKED BY _____



sperry-sun



020673