


WELL 88 VX-04
DEPTH 617
PICTURE NO. 4
INCLINATION 169.8
OBS. DIR. N35E
COR. DIR. 067
TOOL FACE _____
RUN BY _____
DATE Sept 2 '88
CHECKED BY CH



sperry-sun



WELL 88 VX-04
DEPTH 417
PICTURE NO. 5
INCLINATION 172.2
OBS. DIR. N37E
COR. DIR. 059
TOOL FACE _____
RUN BY _____
DATE Sept 2 '88
CHECKED BY CH




sperry-sun



WELL 88 VX-04
DEPTH 217
PICTURE NO. 6
INCLINATION 176.4
OBS. DIR. N18E
COR. DIR. 050
TOOL FACE _____
RUN BY _____
DATE Sept 2 '88
CHECKED BY CH



sperry-sun



WELL 88 VX-04
DEPTH 817
PICTURE NO. 3
INCLINATION 167.0
OBS. DIR. N34E
COR. DIR. 16
TOOL FACE _____
RUN BY _____
DATE Sept 2 '88
CHECKED BY CH



sperry-sun



WELL 88 VX-04
DEPTH 987
PICTURE NO. 1
INCLINATION 164.5
OBS. DIR. N45°E
COR. DIR. 077
TOOL FACE _____
RUN BY _____
DATE Sept 2 '88
CHECKED BY CH



sperry-sun



WELL 88 VX-04
DEPTH 917
PICTURE NO. 2
INCLINATION 164.2
OBS. DIR. N36°E
COR. DIR. 068
TOOL FACE _____
RUN BY _____
DATE Sept 2 '88
CHECKED BY CH



sperry-sun



020676